





FLOATING BATH THERMOMETER

TO USE:

- Ensure that the bath water is mixed throughout so there would be an even temperature distribution.
- Dip completely the bath thermometer into the bath water for 1-2 minutes.
- Wait for a further 5 seconds and read the temperature. Adjust water to reach desired water temperature before putting child in bath.

NOTE: THE RECOMMENDED BATH TEMPERATURE IS GENERALLY BETWEEN 35°C AND 38°C.

IDEAL BATH TEMPERATURE 35-38°C

CAUTION/WARNING:

 Always check water temperature manually in addition to using this thermometer before placing the baby in the bath.

• ATTENTION: NEVER LEAVE THE CHILDREN UNATTENDED IN THE BATH. THERE IS NO SUBSTITUTE FOR ADULT SUPERVISION.

• Keep all components not in use out of reach of children.

 ATTENTION: BEFORE EACH USE, INSPECT THE PRODUCT AND THROW AWAY AT THE FIRST SIGN OF DAMAGE OR WEAKNESS. IF THE COLUMN OF INDICATING LIQUID IN A THERMOMETER SEPARATES - STOP USING THE THERMOMETER.

TO CLEAN:

- Wash the thermometer in warm and soapy water, rinse well and let it dry before using the first time and after each use.
- Wipe clean with soft damp cloth. If required, use mild detergent and dry it well.
- When not in use, store the thermometer in a dry area away from direct sunlight.

TEMPERATURE RANGE	5-45°C
INCREMENTS IN °C	5°C
ACCURACY	+/- 1.5°C

Certified as safe bath toy (EN71 compliant)